Coloreel Studio Software Release v1.2.5

Compared with v1.1.3

Release date: 2022-04-08

General

The new Coloreel Studio software update, version 1.2, has improved functions and fixes to known issues.

A checking tool is added to verify if the design (colors) includes areas with high amount of ink. Areas with high amount of ink can affect the result of the embroidery in a negative way.

The installation wizard and icon in Windows bar is updated with the new Coloreel brand design.

The Coloreel Studio software is now also a certified software meaning that when installing the software, it is showing that the software is generated from Coloreel Group AB (publ).

Main Features

- Implementation of the new Coloreel brand language in the Installation Wizard
- Coloreel Group AB is now digital certified company meaning that Coloreel Studio is released from a known company/source
- The background is now transparent when a thumbnail is created
- When open Gamut Tool colors from timeline are automatically presented
- Check is introduced, if high amount of ink, when saving file
- User can mark and move more than one section to the left or to the right at same time
- User settings saved when closing, example CCP narrow/max setting
- With the use of Tool Tip in palette, the user can see the color properties

Fixes

- Corrected the error that occurred when opening a *.CSE with many empty threads (ZD722)
- Operators can now easily extend the visible bar to its ends after usage
- Stability improvements when updating stitches with new *.DST file
- When closing an unsaved *.CSE design with 'X' in upper right corner the file is saved via pop up window
- It is now possible to open read-only files in Coloreel Studio
- Hot fix v1.2.3: Handling of color change precision parameters in Settings file when upgrading Coloreel Studio from older software version.
- Hot fix v1.2.4: Included new ICC profile and volume limiter, same as is introduced in ITC-U from v1.9. The drop-down menu *Color Proposal* is removed from Soft Proofing Gamut Tool as it is not needed with new ink limiter.
- Hot fix v1.2.5: Digital certified software (installation), soft proofing CCP handling improvements, stitch counter refresh handling.

Known issues

- -

Ink check

When a user of Coloreel Studio saves a design, a check is made to see if there are areas in the file that have colors with high amount of ink. This can, dependent on the material to be embroidered on, affect the result and quality of the design. If there are areas with high amount of ink it will result in an extra dialog box for user to adjust the amount of ink or to ignore and proceed without the adjustment.